

## **BRP 9490 INSTRUCTIONS**

This bolt need to be torqued to 60 ft lbs never seize should be applied to bolt before it is assembled and tightened.



The tab that the torsion stop rests on may need to be ground back a bit to clear the jam nut. on the adjustor